CHECK Compatibility Chart

Gold, Silver, Bronze, Traditional, & Check 21+

		All-in-One/Stand-alone Checks	Check 21+ Support (see double-sided imagers in GREEN)	Welch Allyn	CRM431	CR600	Ingenico eN2500	Magtek Mini MICR	Magtek Mini/Magstripe	Ingenico eN2600	CR1000i	RDM 5003/5004i/6003i/6004i/6014i	Magtek MICR-Image (P/N 22410006 for dial upload & P/N 22410004 for IP upload)	Magtek Excella (Double Sided Imager)	Magtek STX (Double Sided Imager)	RDM eC7000i Series (Double Sided Imager)	P250iP900	Scribe 612	Citizen IDP560/562	Multi-Merchant Capable	IP/Ethernet Support	Wireless Support	Integrated Download File (GETI Must Build For All Processors)	Independent Download File (GETI Build For Check Only)	DL Service Supported (When Magstripe Is Present)	IMPORTANT NOTES
ePN	EPN MICR							●													●					For more information contact ePocessing Network at 800-971-0997 or
	EPN Mobile MICR							●														●				www.eProcessingNetwork.com
ingenico	iVI Checkmanager3000	●															●	●	●					●		Unit must have OS version 2.8 or higher and requires printer for Gold/Silver (cannot use built-in printer from another terminal)…
	i5100, i7780					●	●			●		●								●	●			●	●	IP Image Uploads not available at this time…Bronze/Traditional Service req manual Batch "Clear" for proper reporting…
Lipman	Nurit 2080			4	4	4	5	4									●	●	●	●			●		●	Possible memory limitations may exist…
	Nurit 2060, 2085, 3000, 3020, 8320			4	4	4	5	4			●	4				●				●			●		●	Conflicts between applications/protocols could cause support issues…
	Nurit 2090, 3010, 8000, 8020, 8400 (Dial-up Only)			4	4	4	5	4			●	4				●				●			●		●	
	Valupak 700, 720 w/Built-in Welch Allyn Reader	●		4																●			●		●	Docking Station required to connect check reader/imager to Nurit 8000…
VeriFone	PC Charge (Dial-up Only)							4	4																●	Keyboard Wedge or USB Reader's Only (P/N's 22520001, 22520020, 22530001, 22530005, 22523001, 22523003, 22533001, 22533003)
	Omni 3200, 3200SE, 3210				4	4	5	4			●				●									●	●	3200 is slow to operate within the bankcard app…Known Memory issue with RBS Lynk Softpay bankcard…
	Omni 3730 LE, Vx510 LE	●			4	4	5	4		●	●	4			●					●				●	●	Single Application Terminals and WILL NOT Support Credit, Debit, Gift, etc…With the Check Download…
	Omni 3730, Vx510, Vx570				4	4	5	4		●	●	4			●					●				●	●	3730 and Vx510 will not support more than TWO Applications…Works w/Bankcard & Check, OR Check & Gift ONLY…
	Omni 3300, 3740, 3750				4	4	5	4		●	●	4			●					●				●	●	Requires At least 6 Meg Of Memory For Multiple Add Value Applications…
HYPERCOM	T7E (T7E requires a ext. printer)				4	4	5	4			●				●		●					●				** ALL Hypercom's MUST be on FDR (Omaha), TSYS (VITAL), Global (NDC), Paymentech, Nova, or FDMS (Nashville) **
	T7P, T7Plus, T77				4	4	5	4			●				●				●			●				512 K required for T7 (1 meg for Multi-Merchant)...T77 -G(?) models not supported by GETI's version of SPOS…
	ICE 5500				4	4	5	4			●				●				●			●				
	ICE 5700	●																	●							1 meg required for ICE (1.5 meg for Multi-Merchant)…
	TPI Software/SmartPayments Server							6	●			●							●	●					6	See SmartPayments Hardware Compatibility List for details…
THALES	Talento				4	4	5	4		●		●				●			●					●	3	GETI Cannot build the credit load for Talento Terminals…
RDM	RDM Synergy	●																	●					●	●	
4Access	4Access Orion	●	●																●	●					●	
DIONICA	Dionica Omero X							4			●				●									●	●	
Commerciant	Mobilescape 5000 (Class B)	●																			●				●	Support is handled by Commerciant…
axalto	Axalto Magic 6100 (Class B)(EMS Agents Only)							4			●				●											Support is handled by EMS…
	PrimeTrex IP							●			●				●				●	●				●	●	Auto-Close does not work properly in Multi-App mode…
	GETI Virtual Terminal										●	●			●						●					
	Check21+ Virtual Terminal		●											●	●	●										Currently supports Single Feed Only on Excella...Use eC7011 model RDM's for Check21 (no internal modem needed)...

Bronze & Traditional Only

LinkPoint	LinkPoint 2000, 3000/AIO																	●	●	●				●		FDR Only, and no reader capability on the Linkpoints…
VeriFone	Zon Jr, XL300, Tranz 330, & T380				1	1	1	1																●		See notes below…
	Tranz 380x2				2	2	2	2												●				●		Multi-Merchant limited to 2 (with both sides loaded for checks only)…
	Tranz 420 & Tranz 460				1	1	1	1																●		See notes below…
COMSTAR	Comstar 3010																				●			●		
	Comstar 8000																				●			●		

Revised 7/09/08

1 = Check reader support available w/ "Standalone" check service only. If using both credit and check on the terminal, MICR information must be manually entered.
2 = Full MICR program available w/Check Only service on 2nd side of terminal, otherwise refer to rule 1.
3 = Supported only in certain applications. Please call Technical Support for details.
4 = Configuration Check(s) are required for this check reader/imager.
5 = This Reader must be mailed into Technical Support to be configured.
6 = Requires USB keyboard emulator & keyboard wedge (USB/Wedge).

*** Be advised that we are unable to incorporate our Value Added Services into certain Class A applications/Processors ***
(Please feel free to call Technical Support at 1-877-438-3249 for details/limitations)